

Photo 9: In drydock at Malta, 3 December, 1943.
Temporary repairs to port shell completed.




Photo 10: In drydock at Malta, 3 December, 1943.
Temporary repairs to starboard shell completed.



Photo 11: No. 3 turret gun room - looking forward and to the right.



Photo 12: No. 3 turret gun room - looking aft and to the right.



Photo 13: Looking up to the overhead (first platform level) in the lower handling room A-520-M for No. 3 turret. Note the broken powder hoists. The bulkheads and deck (second platform) were obliterated.




Photo 14: Electric and shell deck, No. 3 turret, showing path of bomb.